



A

F




Caution

Only
Pre Locate







**Do Not Fully
Tighten**



Do Not Fully Tighten





Fully Tighten
12Nm





Caution


Fully Tighten
100Nm














Fully Tighten
40Nm



Repeat Stages

1 - 45

For Left Hand Side



ESSENTIAL CHECKS

It is recommended that periodic inspections are made to ensure that all bolts are tightened to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced



EVOTECH®
P E R F O R M A N C E

www.evotech-performance.com