




Rotate To
Locate




A

B








Caution


Rotate To
Locate








Caution

Do Not Fully Tighten













Do Not Fully Tighten



Do Not Fully Tighten




Fully
Tighten




Caution

Fully
Tighten



Fully
Tighten



Caution

Fully
Tighten



Repeat for R/H Side

1 - 35



ESSENTIAL CHECKS



It is recommended that periodic inspections are made to ensure that all bolts are tightened to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced



EVOTECH®
P E R F O R M A N C E

www.evotech-performance.com