














- |   |   |   |   |
|---|---|---|---|
|  x2 |  x33 |  x14 |  x8  |
|  x2 |  x10 |  x29 |  x25 |





1






2







3






4






5



6






7












8




9







-  x1
-  x14
-  x6
-  x6



10







 x1	 x3
 x4	 x2




1 1



x2










12




13




-  x4
-  x4
-  x2
-  x6
-  x2







14








16



17



x3

x1

x2

A rounded rectangular box containing a parts list. It shows three grey pins, one grey 1x2 Technic connector, and two grey curved Technic connectors. The quantities are listed as x3, x1, and x2 respectively.

