





Do Not Fully Tighten





Do Not Fully Tighten








Repeat
Both Sides




Ensure radiator guard securely hooks over the top lip of the radiator

A small diagram in the bottom left corner shows a cross-section of the radiator guard's top edge. A green arrow points downwards from the top lip of the radiator towards the guard, indicating the direction of installation.


Repeat Both Sides




Repeat
Both Sides




Repeat
Both Sides




Repeat
Both Sides



Repeat
Both Sides



Repeat Both Sides



Fully
Tighten

Repeat
Both Sides



ESSENTIAL CHECKS

It is recommended that periodic inspections are made to ensure that dirt and debris have not become trapped between the guard and the radiator/oil cooler. Such dirt and debris would reduce the cooling efficiency of the radiator/oil cooler.

It is recommended that periodic inspections are made to ensure that all fixings are fully tightened.



EVOTECH®
P E R F O R M A N C E

www.evotech-performance.com